

**HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS**

HAER
CAL
26-JULA.V,
1B-

**Rush Creek Hydroelectric System,
Worker Cottage (Building 103)
Rush Creek
June Lake Vicinity
Mono County
California**

HAER No. CA-166-B

Gregory L. O'Loughlin, photographer

August, 1997

- CA-166-B-1 EXTERIOR OVERVIEW OF SOUTH END OF RUSH CREEK POWERHOUSE RESIDENTIAL COMPLEX SHOWING THE RUSH CREEK POWERHOUSE AT PHOTO RIGHT (TAILRACE IN FOREGROUND), BUILDING 106 NEXT TO THE POWERHOUSE AT PHOTO LEFT CENTER, AND BUILDING 103 AT UPPER PHOTO LEFT ABOVE AND BEHIND BUILDING 106. VIEW TO SOUTH.
- CA-166-B-2 EXTERIOR NORTH END OF BUILDING 103 SHOWING PAVED PARKING AREA BETWEEN BUILDING 103 AND BUILDING 104, AND WALKWAY TO FRONT (EAST SIDE) ENTRY OF HOUSE. VIEW TO SOUTHEAST.
- CA-166-B-3 EXTERIOR OF FRONT ENTRY SHOWING GABLE OVER RECESSED PORCH WITH RUSTIC STYLE DECORATIVE TREATMENT. WELDED STEEL PORCH RAILING ADDED IN 1972 IS VISIBLE AT PHOTO CENTER. VIEW TO SOUTHWEST.
- CA-166-B-4 EXTERIOR OF SOUTH END OF BUILDING 103 SHOWING 1-LIGHT SIDE EXIT DOOR AND ORIGINAL WOOD-FRAMED SLIDING-GLASS KITCHEN WINDOWS AT PHOTO LEFT, CRISS-CROSS WOOD BALUSTRADE AROUND FRONT PORCH WITH OPEN DOOWAY TO BASEMENT BENEATH, AND STONE FACING ALONG ORIGINAL PORTION OF HOUSE FRONT AT PHOTO RIGHT. VIEW TO WEST.
- CA-166-B-5 EXTERIOR OF WEST (REAR) SIDE OF BUILDING 103 SHOWING TALL RUSTIC STYLE CHIMNEY WITH GABLE FRAME, AND CONCRETE STEPS TO SIDE ENTRY DOOR AT PHOTO RIGHT. CHANGE IN EXTERIOR WALL DELINEATING 1946 BEDROOM ADDITION AND REMODELED WINDOW TO BATHROOM ARE VISIBLE AT PHOTO LEFT. VIEW TO NORTHEAST.

RUSH CREEK HYDROELECTRIC SYSTEM
WORKER COTTAGE (BUILDING 103)
HAER No. CA-166-B
INDEX TO PHOTOGRAPHS (Page 2)

- CA-166-B-6 INTERIOR OF UNFINISHED BASEMENT SHOWING CONCRETE FORM IMPRESSIONS ON THE WALLS, AND EXPOSED FLOOR SUPPORT BEAMS. VIEW TO WEST.
- CA-166-B-7 INTERIOR LIVING ROOM SHOWING 6-LIGHT FRONT DOOR FLANKED BY ONE OF TWO 6-LIGHT OVER 1-LIGHT SASH WINDOWS AT PHOTO RIGHT, AND OPEN DOORWAY TO BEDROOM NUMBER ONE (AND BEDROOM NUMBER TWO IN BACKGROUND) AT PHOTO LEFT. VIEW TO NORTH.
- CA-166-B-8 INTERIOR OF LIVING ROOM SHOWING OPEN DOORWAY TO KITCHEN, 6-LIGHT OVER 1-LIGHT SASH WINDOWS ON FRONT WALL AT PHOTO LEFT, AND 6-LIGHT OVER 1-LIGHT SASH WINDOW ON BACK WALL AT EXTREME PHOTO RIGHT. VIEW TO EAST.
- CA-166-B-9 INTERIOR OF LIVING ROOM SHOWING OPEN 6-LIGHT FRONT ENTRY DOOR, OPEN PANEL DOOR TO BEDROOM NUMBER ONE, AND 6-LIGHT OVER 1-LIGHT SASH WINDOW ON REAR WALL AT PHOTO LEFT CENTER. FIREPLACE ORIGINALLY OCCUPIED SPACE UNDER ROUND HEATER VENT HOLE AT PHOTO LEFT. VIEW TO WEST.
- CA-166-B-10 INTERIOR OF BEDROOM NUMBER ONE SHOWING OPEN PANEL DOOR TO LIVING ROOM AT EXTREME PHOTO RIGHT, OPEN DOOR TO BATHROOM AT PHOTO CENTER, AND OPEN PANEL DOOR TO WALK-IN CLOSET AT PHOTO LEFT. VIEW TO NORTHEAST.
- CA-166-B-11 INTERIOR OF BEDROOM NUMBER ONE SHOWING 6-LIGHT OVER 1-LIGHT SASH WINDOW ON EAST WALL. VIEW TO NORTH.
- CA-166-B-12 INTERIOR OF BATHROOM SHOWING UPDATED SHOWER/BATH AND SINK. VIEW TO WEST.
- CA-166-B-13 INTERIOR OF BEDROOM NUMBER TWO SHOWING OPEN PANEL DOOR FROM BEDROOM NUMBER ONE AT PHOTO LEFT, AND OPEN DOORS TO THE TWO SEPARATE WALK-IN CLOSETS AT REAR OF ROOM AT PHOTO CENTER AND RIGHT. VIEW TO SOUTH.

RUSH CREEK HYDROELECTRIC SYSTEM
WORKER COTTAGE (BUILDING I03)
HAER No. CA-166-B
INDEX TO PHOTOGRAPHS (Page 3)

- CA-166-B-14 INTERIOR OF BEDROOM NUMBER TWO SHOWING OPEN DOORS TO WALK-IN CLOSETS, AND 1-LIGHT OVER 1-LIGHT SASH WINDOW ON NORTH WALL. VIEW TO WEST.
- CA-166-B-15 INTERIOR OF KITCHEN SHOWING UPDATED CABINETS, COUNTER TOP, SINK, AND FAUCET, AND ORIGINAL WOOD-FRAMED SLIDING-GLASS WINDOW IN NORTH WALL OVERLOOKING FRONT PORCH. VIEW TO NORTH.
- CA-166-B-16 INTERIOR OF KITCHEN SHOWING UPDATED CABINETS AND ORIGINAL WOOD-FRAMED SLIDING-GLASS WINDOWS OVER SINK. VIEW TO EAST.
- CA-166-B-17 INTERIOR OF KITCHEN SHOWING OPEN 6-LIGHT DOOR TO SIDE-ENTRY UTILITY ROOM AT PHOTO LEFT, AND OPEN DOORWAY TO WALK-IN PANTRY AT PHOTO RIGHT. VIEW TO SOUTH.
- CA-166-B-18 INTERIOR OF PANTRY SHOWING SHELVES AND 1-LIGHT OVER 1-LIGHT SASH WINDOW ON SOUTH WALL. VIEW TO SOUTH.
- CA-166-B-19 INTERIOR OF SIDE-ENTRY UTILITY ROOM SHOWING OPEN 1-LIGHT SIDE-EXIT DOOR AT PHOTO LEFT AND 1-LIGHT OVER 1-LIGHT SASH WINDOW INTO PANTRY AT PHOTO RIGHT. ALCOVE AT PHOTO CENTER WAS ORIGINALLY DESIGNED TO BE A BROOM CLOSET. VIEW TO SOUTHWEST.